

Last modified: 03/03/2020 13:18:43

Fascia Assembly - Front (Remove and Replace)

Correction Code 10011002

Removal

1. Remove the front fascia assembly (refer to procedure) ○ .
2. Remove the fascia valance (refer to procedure) ○ .
3. Remove all park assist sensors (refer to procedure) ○ .
4. Remove the upper grille bright trim and center fascia bracket (refer to procedure) ○ .
5. Remove the upper fog light spears (refer to procedure) ○ .
6. Remove the lower fog light spears (refer to procedure) ○ .

Installation

Installation procedure is the reverse of removal, except for the following:



CAUTION

Care must be taken to avoid damage to paintwork and exterior trim.



CAUTION

Replace any broken clips.

1. Transfer all components to the new front fascia.
2. Perform a radar sensor calibration only if the front radar sensor likely moved outside of its calibration tolerance (due to front end collision, contact while removing the fascia, etc.). See Calibration - Front Radar Sensor ○ .

**Note**

If radar sensor calibration is required, add the correction code separately.